

# Nilfisk **FOOD**

## Software Change

### Log

BF8-P

BF4-P

BW7-P

BW4-P

BF16

BF24

BF32

MU4xx-P

MD4xx-P

MIX10-P

MIX25-P



# Software Change Log



Valid for the following models:

- BF8-P MU4xx-P
- BF4-P MD4xx-P
- BW7-P MIX10-P
- BW4-P MIX25-P
- BF16
- BF24
- BF32

Log:		
Display software version	Changes	Software Manual Date
5.21	Power up error for Mix10 and Mix25 removed Handling of Warning and Errors improved Improved communication stability	09/2022
5.20	MIX10 and MIX25 option now available in display (requires inverter software min 2.10). C1 error description corrected and improved. Minor improvements in communication.	Mix Software manual 08/2022 Mainstations and SB 07/2022 Multiboosters 07/2022
5.15	Communication for multiboosters improved.	
5.14	Menu for Pegasus/Compact and PRO was incorrect.	
5.13	Optimized switch between pump start.	
5.12	Multibooster types implemented in default software.	
5.04	Change device type improved.	
5.03	Bug in analogue set point corrected. Readout of analogue setpoint improved.	07/21
5.02	Initial version	