
Nilfisk FOOD

Software Change Log

Multi Booster

V4.15



Software Change Log



Valid for the following models:

- Multi Booster BF16-48
- Multi Booster BF16T 48T

Display 4.0x:

Can not be upgraded to 4.10 or higher.

Upgrade path:

- Always upgrade to newest version - NEVER downgrade!

Log:		
Display & Controller software version	Changes	Software Manual Date
4.15	Tank control functionality improved, minor bug fixes	10.06.2016
4.14	Delayed start is activated when supply tank is activated. Some text updates. All values will be set to default if software is upgraded to this version, e.g. num- ber of pumps will be set to 2.	10.06.2016
4.13	Measured pressure could in some cases show a corrupt value.	10.06.2016
4.12	Default brand changed to Nilfisk FOOD.	
4.11	New functionality at relay OUT1. Both internal and external tank control. PT1000 Option. Nilfisk Alto changed to Nilfisk FOOD. Minor bug fixes.	
4.10	New bootloader, both Hybrid, Pegasus, MB, Airspexx and Cerberus are now using the same bootloader. Minor bug fixes.	