

Service Information no. 184

Chameleon Flow Sensor Sealing - improved December 2008

Models: MM, MP, BW, BF and SA

To minimize the risk of vibrations influencing the flow sensor, Grundfos has added an extra sealing. Please see the pictures below.



Here you can see the two sealing rings:
The new green sealing ring has been added in order to avoid vibrations.

Below pictures illustrate that the green sealing ring is visible when mounted



Please be aware that it might be difficult to mount the sensor with the new sealing!
If it is too tight, please make a small deburring.

Should you need any further information do not hesitate to contact
Nilfisk-ALTO Food Division sales department, direct tel. No.: +45 7218 2000.

Best regards
Nilfisk-ALTO Food Division

Niels Chr. Thygesen
Dir. tel.: +45 7218 2006/Niels.Thygesen@nilfisk-alto.com