
Nilfisk 6000

Software Change Log

Hybrid Typhoon

V1.04



Software Change Log



Valid for the following models:

- Hybrid Typhoon Hybrid Typhoon 40

Upgrade path:

- Always upgrade to newest version - NEVER downgrade!

Log:	
Display & Controller software version	Changes
1.04	Both Ecolab and Nilfisk variants are now available. Different software but same functionality.
1.03	Phase sequence detection implemented, for detection of correct function of compressor.
1.02	Readout of software version possible when OK button is pressend and unitis in "OFF" (red button). Minor bug fixes.
1.01	Version number changed so that it is possible to differentiate between no communication and version 1.00
1.00	Initial version of software.