



Software Change Log



Valid for the following models:

- MH42, MP42, BF16, BF24, BF32, BF4, BF8, BH4, BP4, BH7, Hybrid 7 Foamatic mainstation and satellite

- Always upgrade to newest version - NEVER downgrade!

Log:	
Inverter software version	Changes
2.12	Delayed start improved: Error output reacts on display errors
2.11	Changes to bootloader
2.10	Initial version